

## Not Recommended for New Designs (NRND) Announcement

### TMR 2WI series

To whom it may concern,

We inform you, that TMR 2WI series is no longer recommended for new designs\*.

In case you have any questions, please contact your TRACO POWER distributor or directly approach the [TRACO POWER Sales and Support](#) teams\*\*.

We thank you for your consideration.

Matthias Landolt  
Product Management

\* Traco Power is committed to keeping products in the market as long as possible. A status change to NRND (not recommended for new designs) is not in all cases indicative of an imminent end of life (EOL).

\*\* Customers may also register for the <<Keep Me Updated>> feature available on our individual product websites. This feature serves for receipt of real-time technical or status related product change notifications.

\*\*\* Product options not explicitly listed but included in the status change notification

## Appendix 1 - Possible Replacements

Affected models***	Potential Replacements	
TMR 2-2410WI	TEC 2-2410WI	TMR 2-2410WIN
TMR 2-2411WI	TEC 2-2411WI	TMR 2-2411WIN
TMR 2-2412WI	TEC 2-2412WI	TMR 2-2412WIN
TMR 2-2413WI	TEC 2-2413WI	TMR 2-2413WIN
TMR 2-2421WI	TEC 2-2421WI	TMR 2-2421WIN
TMR 2-2422WI	TEC 2-2422WI	TMR 2-2422WIN
TMR 2-2423WI	TEC 2-2423WI	TMR 2-2423WIN
TMR 2-4810WI	TEC 2-4810WI	TMR 2-4810WIN
TMR 2-4811WI	TEC 2-4811WI	TMR 2-4811WIN
TMR 2-4812WI	TEC 2-4812WI	TMR 2-4812WIN
TMR 2-4813WI	TEC 2-4813WI	TMR 2-4813WIN
TMR 2-4821WI	TEC 2-4821WI	TMR 2-4821WIN
TMR 2-4822WI	TEC 2-4822WI	TMR 2-4822WIN
TMR 2-4823WI	TEC 2-4823WI	TMR 2-4823WIN

\* Traco Power is committed to keeping products in the market as long as possible. A status change to NRND (not recommended for new designs) is not in all cases indicative of an imminent end of life (EOL).

\*\* Customers may also register for the <<Keep Me Updated>> feature available on our individual product websites. This feature serves for receipt of real-time technical or status related product change notifications.

\*\*\* Product options not explicitly listed but included in the status change notification