

CERTIFICATE OF COMPLIANCE

Certificate Number E188913
Report Reference E188913-20210203
Issue Date 2022-March-16

Issued to: TRACO ELECTRONIC AG
Sihlbruggstrasse 111
Baar, CH-6340

**This certificate confirms that
representative samples of**

POWER SUPPLIES FOR USE WITH AUDIO/VIDEO,
INFORMATION AND COMMUNICATION TECHNOLOGY
EQUIPMENT - COMPONENT
See addendum page for models

Have been investigated by UL in accordance with the
component requirements in the Standard(s) indicated on
this Certificate. UL Recognized components are incomplete
in certain constructional features or restricted in
performance capabilities and are intended for installation in
complete equipment submitted for investigation to UL LLC.

Standard(s) for Safety: UL 62368-1 & CAN/CSA C22.2 No. 62368-1-14 -
Audio/video, Information and Communication Technology
Equipment - Part 1: Safety Requirements

Additional Information: See the UL Online Certifications Directory at
<https://iq.ulprospector.com> for additional information.

This *Certificate of Compliance* does not provide authorization to apply the UL Recognized Component Mark. Only
the UL Follow-Up Services Procedure provides authorization to apply the UL Mark.

Only those products bearing the UL Recognized Component Mark should be considered as being UL Certified
and covered under UL's Follow-Up Services.

Look for the UL Recognized Component Mark on the product.



Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please
contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>




CERTIFICATE OF COMPLIANCE

Certificate Number E188913
Report Reference E188913-20210203
Issue Date 2022-March-16

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements.

TPP 40-105Azzzzzzzz
TPP 40-107Azzzzzzzz
TPP 40-109Azzzzzzzz
TPP 40-112Azzzzzzzz
TPP 40-1L12Azzzzzzzz
TPP 40-115Azzzzzzzz
TPP 40-1L15Azzzzzzzz
TPP 40-124Azzzzzzzz
TPP 40-128Azzzzzzzz
TPP 40-136Azzzzzzzz
TPP 40-148Azzzzzzzz
TPP 40-153Azzzzzzzz
TPP 40-105Uzzzzzzzz
TPP 40-107Uzzzzzzzz
TPP 40-109Uzzzzzzzz
TPP 40-112Uzzzzzzzz
TPP 40-1L12Uzzzzzzzz
TPP 40-115Uzzzzzzzz
TPP 40-1L15Uzzzzzzzz
TPP 40-124Uzzzzzzzz
TPP 40-128Uzzzzzzzz
TPP 40-136Uzzzzzzzz
TPP 40-148Uzzzzzzzz
TPP 40-153Uzzzzzzzz
TPP 40-105zzzzzzzz
TPP 40-107zzzzzzzz
TPP 40-109zzzzzzzz
TPP 40-112zzzzzzzz
TPP 40-1L12zzzzzzzz
TPP 40-115zzzzzzzz
TPP 40-1L15zzzzzzzz
TPP 40-124zzzzzzzz
TPP 40-128zzzzzzzz
TPP 40-136zzzzzzzz
TPP 40-148zzzzzzzz
TPP 40-153zzzzzzzz
TPP 40-105Dzzzzzzzz
TPP 40-107Dzzzzzzzz
TPP 40-109Dzzzzzzzz
TPP 40-112Dzzzzzzzz



Bruce Mahrenholz, Director North American Certification Program

UL LLC


Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



CERTIFICATE OF COMPLIANCE

Certificate Number E188913
Report Reference E188913-20210203
Issue Date 2022-March-16

TPP 40-1L12Dzzzzzzzz
TPP 40-115Dzzzzzzzz
TPP 40-1L15Dzzzzzzzz
TPP 40-124Dzzzzzzzz
TPP 40-128Dzzzzzzzz
TPP 40-136Dzzzzzzzz
TPP 40-148Dzzzzzzzz
TPP 40-153Dzzzzzzzz
TPP 40-105E-Dzzzzzzzz
TPP 40-107E-Dzzzzzzzz
TPP 40-109E-Dzzzzzzzz
TPP 40-112E-Dzzzzzzzz
TPP 40-112E-DB1zzzzzzzz
TPP 40-115E-Dzzzzzzzz
TPP 40-115E-DB1zzzzzzzz
TPP 40-118E-Dzzzzzzzz
TPP 40-124E-Dzzzzzzzz
TPP 40-128E-Dzzzzzzzz
TPP 40-136E-Dzzzzzzzz
TPP 40-148E-Dzzzzzzzz
TPP 40-153E-Dzzzzzzzz
TPP 40-105E-Jzzzzzzzz
TPP 40-107E-Jzzzzzzzz
TPP 40-109E-Jzzzzzzzz
TPP 40-112E-Jzzzzzzzz
TPP 40-112E-JB1zzzzzzzz
TPP 40-115E-Jzzzzzzzz
TPP 40-115E-JB1zzzzzzzz
TPP 40-118E-Jzzzzzzzz
TPP 40-124E-Jzzzzzzzz
TPP 40-128E-Jzzzzzzzz
TPP 40-136E-Jzzzzzzzz
TPP 40-148E-Jzzzzzzzz
TPP 40-153E-Jzzzzzzzz
TPP 65-105E-Dzzzzzzzz
TPP 65-107E-Dzzzzzzzz
TPP 65-109E-Dzzzzzzzz
TPP 65-112E-Dzzzzzzzz
TPP 65-115E-Dzzzzzzzz
TPP 65-118E-Dzzzzzzzz
TPP 65-124E-Dzzzzzzzz
TPP 65-124E-DB1zzzzzzzz
TPP 65-128E-Dzzzzzzzz
TPP 65-128E-DB1zzzzzzzz



Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



CERTIFICATE OF COMPLIANCE

Certificate Number E188913
Report Reference E188913-20210203
Issue Date 2022-March-16

TPP 65-136E-Dzzzzzzzz
TPP 65-148E-Dzzzzzzzz
TPP 65-153E-Dzzzzzzzz
TPP 65-105E-Jzzzzzzzz
TPP 65-107E-Jzzzzzzzz
TPP 65-109E-Jzzzzzzzz
TPP 65-112E-Jzzzzzzzz
TPP 65-115E-Jzzzzzzzz
TPP 65-118E-Jzzzzzzzz
TPP 65-124E-Jzzzzzzzz
TPP 65-124E-JB1zzzzzzzz
TPP 65-128E-Jzzzzzzzz
TPP 65-128E-JB1zzzzzzzz
TPP 65-136E-Jzzzzzzzz
TPP 65-148E-Jzzzzzzzz
TPP 65-153E-Jzzzzzzzz
TPP 40-105BAzzzzzzzz
TPP 40-107BAzzzzzzzz
TPP 40-109BAzzzzzzzz
TPP 40-112BAzzzzzzzz
TPP 40-1L12BAzzzzzzzz
TPP 40-115BAzzzzzzzz
TPP 40-1L15BAzzzzzzzz
TPP 40-124BAzzzzzzzz
TPP 40-128BAzzzzzzzz
TPP 40-136BAzzzzzzzz
TPP 40-148BAzzzzzzzz
TPP 40-153BAzzzzzzzz
TPP 40-105BUzzzzzzzz
TPP 40-107BUzzzzzzzz
TPP 40-109BUzzzzzzzz
TPP 40-112BUzzzzzzzz
TPP 40-1L12BUzzzzzzzz
TPP 40-115BUzzzzzzzz
TPP 40-1L15BUzzzzzzzz
TPP 40-124BUzzzzzzzz
TPP 40-128BUzzzzzzzz
TPP 40-136BUzzzzzzzz
TPP 40-148BUzzzzzzzz
TPP 40-153BUzzzzzzzz
TPP 40-105Bzzzzzzzz
TPP 40-107Bzzzzzzzz
TPP 40-109Bzzzzzzzz
TPP 40-112Bzzzzzzzz



Bruce Mahrenholz, Director North American Certification Program

UL LLC


Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



CERTIFICATE OF COMPLIANCE

Certificate Number E188913
Report Reference E188913-20210203
Issue Date 2022-March-16

TPP 40-1L12Bzzzzzzzz
TPP 40-115Bzzzzzzzz
TPP 40-1L15Bzzzzzzzz
TPP 40-124Bzzzzzzzz
TPP 40-128Bzzzzzzzz
TPP 40-136Bzzzzzzzz
TPP 40-148Bzzzzzzzz
TPP 40-153Bzzzzzzzz
TPP 40-105BDzzzzzzzz
TPP 40-107BDzzzzzzzz
TPP 40-109BDzzzzzzzz
TPP 40-112BDzzzzzzzz
TPP 40-1L12BDzzzzzzzz
TPP 40-115BDzzzzzzzz
TPP 40-1L15BDzzzzzzzz
TPP 40-124BDzzzzzzzz
TPP 40-128BDzzzzzzzz
TPP 40-136BDzzzzzzzz
TPP 40-148BDzzzzzzzz
TPP 40-153BDzzzzzzzz
TPP 65-105BAzzzzzzzz
TPP 65-107BAzzzzzzzz
TPP 65-109BAzzzzzzzz
TPP 65-112BAzzzzzzzz
TPP 65-115BAzzzzzzzz
TPP 65-124BAzzzzzzzz
TPP 65-1L24BAzzzzzzzz
TPP 65-128BAzzzzzzzz
TPP 65-1L28BAzzzzzzzz
TPP 65-136BAzzzzzzzz
TPP 65-148BAzzzzzzzz
TPP 65-153BAzzzzzzzz
TPP 65-105BUzzzzzzzz
TPP 65-107BUzzzzzzzz
TPP 65-109BUzzzzzzzz
TPP 65-112BUzzzzzzzz
TPP 65-115BUzzzzzzzz
TPP 65-124BUzzzzzzzz
TPP 65-1L24BUzzzzzzzz
TPP 65-128BUzzzzzzzz
TPP 65-1L28BUzzzzzzzz
TPP 65-136BUzzzzzzzz
TPP 65-148BUzzzzzzzz
TPP 65-153BUzzzzzzzz



Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



CERTIFICATE OF COMPLIANCE

Certificate Number E188913
Report Reference E188913-20210203
Issue Date 2022-March-16

TPP 65-105Bzzzzzzzz
TPP 65-107Bzzzzzzzz
TPP 65-109Bzzzzzzzz
TPP 65-112Bzzzzzzzz
TPP 65-115Bzzzzzzzz
TPP 65-124Bzzzzzzzz
TPP 65-1L24Bzzzzzzzz
TPP 65-128Bzzzzzzzz
TPP 65-1L28Bzzzzzzzz
TPP 65-136Bzzzzzzzz
TPP 65-148Bzzzzzzzz
TPP 65-153Bzzzzzzzz
TPP 65-105BDzzzzzzzz
TPP 65-107BDzzzzzzzz
TPP 65-109BDzzzzzzzz
TPP 65-112BDzzzzzzzz
TPP 65-115BDzzzzzzzz
TPP 65-124BDzzzzzzzz
TPP 65-1L24BDzzzzzzzz
TPP 65-128BDzzzzzzzz
TPP 65-1L28BDzzzzzzzz
TPP 65-136BDzzzzzzzz
TPP 65-148BDzzzzzzzz
TPP 65-153BDzzzzzzzz
TPP 40-210BAzzzzzzzz
TPP 40-221BAzzzzzzzz
TPP 40-220BAzzzzzzzz
TPP 40-231BAzzzzzzzz
TPP 40-251BAzzzzzzzz
TPP 40-310M1BAzzzzzzzz
TPP 40-3102BAzzzzzzzz
TPP 40-310M2BAzzzzzzzz
TPP 40-321M1BAzzzzzzzz
TPP 40-321M2BAzzzzzzzz
TPP 40-3201BAzzzzzzzz
TPP 40-320M2BAzzzzzzzz
TPP 40-331M3BAzzzzzzzz
TPP 40-3512BAzzzzzzzz
TPP 40-351M2BAzzzzzzzz
TPP 40-210BUzzzzzzzz
TPP 40-221BUzzzzzzzz
TPP 40-220BUzzzzzzzz
TPP 40-231BUzzzzzzzz
TPP 40-251BUzzzzzzzz

B. Mahlenz

Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



CERTIFICATE OF COMPLIANCE

Certificate Number E188913
Report Reference E188913-20210203
Issue Date 2022-March-16

TPP 40-310M1BUzzzzzzzz
TPP 40-3102BUzzzzzzzz
TPP 40-310M2BUzzzzzzzz
TPP 40-321M1BUzzzzzzzz
TPP 40-321M2BUzzzzzzzz
TPP 40-3201BUzzzzzzzz
TPP 40-320M2BUzzzzzzzz
TPP 40-331M3BUzzzzzzzz
TPP 40-3512BUzzzzzzzz
TPP 40-351M2BUzzzzzzzz
TPP 40-210Bzzzzzzzz
TPP 40-221Bzzzzzzzz
TPP 40-220Bzzzzzzzz
TPP 40-231Bzzzzzzzz
TPP 40-251Bzzzzzzzz
TPP 40-310M1Bzzzzzzzz
TPP 40-3102Bzzzzzzzz
TPP 40-310M2Bzzzzzzzz
TPP 40-321M1Bzzzzzzzz
TPP 40-321M2Bzzzzzzzz
TPP 40-3201Bzzzzzzzz
TPP 40-320M2Bzzzzzzzz
TPP 40-331M3Bzzzzzzzz
TPP 40-3512Bzzzzzzzz
TPP 40-351M2Bzzzzzzzz
TPP 40-210BDzzzzzzzz
TPP 40-221BDzzzzzzzz
TPP 40-220BDzzzzzzzz
TPP 40-231BDzzzzzzzz
TPP 40-251BDzzzzzzzz
TPP 40-310M1BDzzzzzzzz
TPP 40-3102BDzzzzzzzz
TPP 40-310M2BDzzzzzzzz
TPP 40-321M1BDzzzzzzzz
TPP 40-321M2BDzzzzzzzz
TPP 40-3201BDzzzzzzzz
TPP 40-320M2BDzzzzzzzz
TPP 40-331M3BDzzzzzzzz
TPP 40-3512BDzzzzzzzz
TPP 40-351M2BDzzzzzzzz
TPP 65-210BAzzzzzzzz
TPP 65-221BAzzzzzzzz
TPP 65-220BAzzzzzzzz
TPP 65-231BAzzzzzzzz

B. Mahlenz

Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



CERTIFICATE OF COMPLIANCE

Certificate Number E188913
Report Reference E188913-20210203
Issue Date 2022-March-16

TPP 65-251BAzzzzzzzz
TPP 65-310M1BAzzzzzzzz
TPP 65-3102BAzzzzzzzz
TPP 65-310M2BAzzzzzzzz
TPP 65-321M1BAzzzzzzzz
TPP 65-321M2BAzzzzzzzz
TPP 65-3201BAzzzzzzzz
TPP 65-320M2BAzzzzzzzz
TPP 65-331M3BAzzzzzzzz
TPP 65-3512BAzzzzzzzz
TPP 65-351M2BAzzzzzzzz
TPP 65-210BUzzzzzzzz
TPP 65-221BUzzzzzzzz
TPP 65-220BUzzzzzzzz
TPP 65-231BUzzzzzzzz
TPP 65-251BUzzzzzzzz
TPP 65-310M1BUzzzzzzzz
TPP 65-3102BUzzzzzzzz
TPP 65-310M2BUzzzzzzzz
TPP 65-321M1BUzzzzzzzz
TPP 65-321M2BUzzzzzzzz
TPP 65-3201BUzzzzzzzz
TPP 65-320M2BUzzzzzzzz
TPP 65-331M3BUzzzzzzzz
TPP 65-3512BUzzzzzzzz
TPP 65-351M2BUzzzzzzzz
TPP 65-210Bzzzzzzzz
TPP 65-221Bzzzzzzzz
TPP 65-220Bzzzzzzzz
TPP 65-231Bzzzzzzzz
TPP 65-251Bzzzzzzzz
TPP 65-310M1Bzzzzzzzz
TPP 65-3102Bzzzzzzzz
TPP 65-310M2Bzzzzzzzz
TPP 65-321M1Bzzzzzzzz
TPP 65-321M2Bzzzzzzzz
TPP 65-3201Bzzzzzzzz
TPP 65-320M2Bzzzzzzzz
TPP 65-331M3Bzzzzzzzz
TPP 65-3512Bzzzzzzzz
TPP 65-351M2Bzzzzzzzz
TPP 65-210BDzzzzzzzz
TPP 65-221BDzzzzzzzz
TPP 65-220BDzzzzzzzz

B. Mahlenz

Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



CERTIFICATE OF COMPLIANCE

Certificate Number E188913
Report Reference E188913-20210203
Issue Date 2022-March-16

TPP 65-231BDzzzzzzzz
TPP 65-251BDzzzzzzzz
TPP 65-310M1BDzzzzzzzz
TPP 65-3102BDzzzzzzzz
TPP 65-310M2BDzzzzzzzz
TPP 65-321M1BDzzzzzzzz
TPP 65-321M2BDzzzzzzzz
TPP 65-3201BDzzzzzzzz
TPP 65-320M2BDzzzzzzzz
TPP 65-331M3BDzzzzzzzz
TPP 65-3512BDzzzzzzzz
TPP 65-351M2BDzzzzzzzz
TPP 40-118BAzzzzzzzz
TPP 40-118BUzzzzzzzz
TPP 40-118Bzzzzzzzz
TPP 40-118BDzzzzzzzz
TPP 65-118BAzzzzzzzz
TPP 65-118BUzzzzzzzz
TPP 65-118Bzzzzzzzz
TPP 65-118BDzzzzzzzz

Note: "z" may be any alphanumeric character, "-" or blank for market purpose.

TPP150-112BAzzzzzz
TPP150-115BAzzzzzz
TPP150-124BAzzzzzz
TPP150-128BAzzzzzz
TPP150-136BAzzzzzz
TPP150-148BAzzzzzz
TPP150-112BUzzzzzz
TPP150-115BUzzzzzz
TPP150-124BUzzzzzz
TPP150-128BUzzzzzz
TPP150-136BUzzzzzz
TPP150-148BUzzzzzz
TPP150-112Bzzzzzz
TPP150-115Bzzzzzz
TPP150-124Bzzzzzz
TPP150-128Bzzzzzz
TPP150-136Bzzzzzz
TPP150-148Bzzzzzz
TPP150-112BDzzzzzz
TPP150-115BDzzzzzz
TPP150-124BDzzzzzz
TPP150-128BDzzzzzz



Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



CERTIFICATE OF COMPLIANCE

Certificate Number E188913
Report Reference E188913-20210203
Issue Date 2022-March-16

TPP150-136BDzzzzzz
TPP150-148BDzzzzzz
TPP100-112BAzzzzzz
TPP100-115BAzzzzzz
TPP100-124BAzzzzzz
TPP100-128BAzzzzzz
TPP100-136BAzzzzzz
TPP100-148BAzzzzzz
TPP100-112BUzzzzzz
TPP100-115BUzzzzzz
TPP100-124BUzzzzzz
TPP100-128BUzzzzzz
TPP100-136BUzzzzzz
TPP100-148BUzzzzzz
TPP100-112Bzzzzzz
TPP100-115Bzzzzzz
TPP100-124Bzzzzzz
TPP100-128Bzzzzzz
TPP100-136Bzzzzzz
TPP100-148Bzzzzzz
TPP100-112BDzzzzzz
TPP100-115BDzzzzzz
TPP100-124BDzzzzzz
TPP100-128BDzzzzzz
TPP100-136BDzzzzzz
TPP100-148BDzzzzzz
TPI150-112BAzzzzzz
TPI150-115BAzzzzzz
TPI150-124BAzzzzzz
TPI150-128BAzzzzzz
TPI150-136BAzzzzzz
TPI150-148BAzzzzzz
TPI150-112BUzzzzzz
TPI150-115BUzzzzzz
TPI150-124BUzzzzzz
TPI150-128BUzzzzzz
TPI150-136BUzzzzzz
TPI150-148BUzzzzzz
TPI150-112Bzzzzzz
TPI150-115Bzzzzzz
TPI150-124Bzzzzzz
TPI150-128Bzzzzzz
TPI150-136Bzzzzzz
TPI150-148Bzzzzzz



Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



CERTIFICATE OF COMPLIANCE

Certificate Number E188913
Report Reference E188913-20210203
Issue Date 2022-March-16

TPI150-112BDzzzzzz
TPI150-115BDzzzzzz
TPI150-124BDzzzzzz
TPI150-128BDzzzzzz
TPI150-136BDzzzzzz
TPI150-148BDzzzzzz
TPI100-148Dzzzzzz
TPI100-112BAzzzzzz
TPI100-115BAzzzzzz
TPI100-124BAzzzzzz
TPI100-128BAzzzzzz
TPI100-136BAzzzzzz
TPI100-148BAzzzzzz
TPI100-112BUzzzzzz
TPI100-115BUzzzzzz
TPI100-124BUzzzzzz
TPI100-128BUzzzzzz
TPI100-136BUzzzzzz
TPI100-148BUzzzzzz
TPI100-112Bzzzzzz
TPI100-115Bzzzzzz
TPI100-124Bzzzzzz
TPI100-128Bzzzzzz
TPI100-136Bzzzzzz
TPI100-148Bzzzzzz
TPI100-112BDzzzzzz
TPI100-115BDzzzzzz
TPI100-124BDzzzzzz
TPI100-128BDzzzzzz
TPI100-136BDzzzzzz
TPI100-148BDzzzzzz
TPP150-112Azzzzzz
TPP150-115Azzzzzz
TPP150-124Azzzzzz
TPP150-128Azzzzzz
TPP150-136Azzzzzz
TPP150-148Azzzzzz
TPP150-112Uzzzzzz
TPP150-115Uzzzzzz
TPP150-124Uzzzzzz
TPP150-128Uzzzzzz
TPP150-136Uzzzzzz
TPP150-148Uzzzzzz
TPP150-112zzzzzz

B. Mahlenz

Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



CERTIFICATE OF COMPLIANCE

Certificate Number E188913
Report Reference E188913-20210203
Issue Date 2022-March-16

TPP150-115zzzzzz
TPP150-124zzzzzz
TPP150-128zzzzzz
TPP150-136zzzzzz
TPP150-148zzzzzz
TPP150-112Dzzzzzz
TPP150-115Dzzzzzz
TPP150-124Dzzzzzz
TPP150-128Dzzzzzz
TPP150-136Dzzzzzz
TPP150-148Dzzzzzz
TPP100-112Azzzzzz
TPP100-115Azzzzzz
TPP100-124Azzzzzz
TPP100-128Azzzzzz
TPP100-136Azzzzzz
TPP100-148Azzzzzz
TPP100-112Uzzzzzz
TPP100-115Uzzzzzz
TPP100-124Uzzzzzz
TPP100-128Uzzzzzz
TPP100-136Uzzzzzz
TPP100-148Uzzzzzz
TPP100-112zzzzzz
TPP100-115zzzzzz
TPP100-124zzzzzz
TPP100-128zzzzzz
TPP100-136zzzzzz
TPP100-148zzzzzz
TPP100-112Dzzzzzz
TPP100-115Dzzzzzz
TPP100-124Dzzzzzz
TPP100-128Dzzzzzz
TPP100-136Dzzzzzz
TPP100-148Dzzzzzz
TPI150-112Azzzzzz
TPI150-115Azzzzzz
TPI150-124Azzzzzz
TPI150-128Azzzzzz
TPI150-136Azzzzzz
TPI150-148Azzzzzz
TPI150-112Uzzzzzz
TPI150-115Uzzzzzz
TPI150-124Uzzzzzz

B. Mahlenz

Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



CERTIFICATE OF COMPLIANCE

Certificate Number E188913
Report Reference E188913-20210203
Issue Date 2022-March-16

TPI150-128Uzzzzzz
TPI150-136Uzzzzzz
TPI150-148Uzzzzzz
TPI150-112zzzzzz
TPI150-115zzzzzz
TPI150-124zzzzzz
TPI150-128zzzzzz
TPI150-136zzzzzz
TPI150-148zzzzzz
TPI150-112Dzzzzzz
TPI150-115Dzzzzzz
TPI150-124Dzzzzzz
TPI150-128Dzzzzzz
TPI150-136Dzzzzzz
TPI150-148Dzzzzzz
TPI100-112Azzzzzz
TPI100-115Azzzzzz
TPI100-124Azzzzzz
TPI100-128Azzzzzz
TPI100-136Azzzzzz
TPI100-148Azzzzzz
TPI100-112Uzzzzzz
TPI100-115Uzzzzzz
TPI100-124Uzzzzzz
TPI100-128Uzzzzzz
TPI100-136Uzzzzzz
TPI100-148Uzzzzzz
TPI100-112zzzzzz
TPI100-115zzzzzz
TPI100-124zzzzzz
TPI100-128zzzzzz
TPI100-136zzzzzz
TPI100-148zzzzzz
TPI100-112Dzzzzzz
TPI100-115Dzzzzzz
TPI100-124Dzzzzzz
TPI100-128Dzzzzzz
TPI100-136Dzzzzzz

z = alphanumeric, "-", "/" or blank for marketing purposes

TPI 125-112Azzzzzz
TPI 125-115Azzzzzz
TPI 125-118Azzzzzz
TPI 125-124Azzzzzz

B. Mahlen

Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



CERTIFICATE OF COMPLIANCE

Certificate Number E188913
Report Reference E188913-20210203
Issue Date 2022-March-16

TPI 125-128Azzzzzzz

TPI 125-136Azzzzzzz

TPI 125-148Azzzzzzz

z = alphanumeric, "-", "/" or blank for marketing purposes.

TPI 30-103Azzzzzzz

TPI 30-105Azzzzzzz

TPI 30-107Azzzzzzz

TPI 30-109Azzzzzzz

TPI 30-112Azzzzzzz

TPI 30-112.1Azzzzzzz

TPI 30-115Azzzzzzz

TPI 30-115.1Azzzzzzz

TPI 30-118Azzzzzzz

TPI 30-124Azzzzzzz

TPI 30-128Azzzzzzz

TPI 30-136Azzzzzzz

TPI 30-148Azzzzzzz

TPI 30-153Azzzzzzz

z = alphanumeric, "-", "/" or blank for marketing purposes.

Switching power supply-Class II

TPP 65-105Azzzzzzzz

TPP 65-107Azzzzzzzz

TPP 65-109Azzzzzzzz

TPP 65-112Azzzzzzzz

TPP 65-115Azzzzzzzz

TPP 65-124Azzzzzzzz

TPP 65-1L24Azzzzzzzz

TPP 65-128Azzzzzzzz

TPP 65-1L28Azzzzzzzz

TPP 65-136Azzzzzzzz

TPP 65-148Azzzzzzzz

TPP 65-153Azzzzzzzz

TPP 65-105Uzzzzzzzz

TPP 65-107Uzzzzzzzz

TPP 65-109Uzzzzzzzz

TPP 65-112Uzzzzzzzz

TPP 65-115Uzzzzzzzz

TPP 65-124Uzzzzzzzz

TPP 65-1L24Uzzzzzzzz

TPP 65-128Uzzzzzzzz



Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



CERTIFICATE OF COMPLIANCE

Certificate Number E188913
Report Reference E188913-20210203
Issue Date 2022-March-16

TPP 65-1L28Uzzzzzzzz
TPP 65-136Uzzzzzzzz
TPP 65-148Uzzzzzzzz
TPP 65-153Uzzzzzzzz
TPP 65-105zzzzzzzz
TPP 65-107zzzzzzzz
TPP 65-109zzzzzzzz
TPP 65-112zzzzzzzz
TPP 65-115zzzzzzzz
TPP 65-124zzzzzzzz
TPP 65-1L24zzzzzzzz
TPP 65-128zzzzzzzz
TPP 65-1L28zzzzzzzz
TPP 65-136zzzzzzzz
TPP 65-148zzzzzzzz
TPP 65-153zzzzzzzz
TPP 65-105Dzzzzzzzz
TPP 65-107Dzzzzzzzz
TPP 65-109Dzzzzzzzz
TPP 65-112Dzzzzzzzz
TPP 65-115Dzzzzzzzz
TPP 65-124Dzzzzzzzz
TPP 65-1L24Dzzzzzzzz
TPP 65-128Dzzzzzzzz
TPP 65-1L28Dzzzzzzzz
TPP 65-136Dzzzzzzzz
TPP 65-148Dzzzzzzzz
TPP 65-153Dzzzzzzzz
TPP 40-210Azzzzzzzz
TPP 40-221Azzzzzzzz
TPP 40-220Azzzzzzzz
TPP 40-231Azzzzzzzz
TPP 40-251Azzzzzzzz
TPP 40-310M1Azzzzzzzz
TPP 40-3102Azzzzzzzz
TPP 40-310M2Azzzzzzzz
TPP 40-321M1Azzzzzzzz
TPP 40-321M2Azzzzzzzz
TPP 40-3201Azzzzzzzz
TPP 40-320M2Azzzzzzzz
TPP 40-331M3Azzzzzzzz
TPP 40-3512Azzzzzzzz
TPP 40-351M2Azzzzzzzz
TPP 40-210Uzzzzzzzz

B. Mahrenholz

Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



CERTIFICATE OF COMPLIANCE

Certificate Number E188913
Report Reference E188913-20210203
Issue Date 2022-March-16

TPP 40-221Uzzzzzzzz
TPP 40-220Uzzzzzzzz
TPP 40-231Uzzzzzzzz
TPP 40-251Uzzzzzzzz
TPP 40-310M1Uzzzzzzzz
TPP 40-3102Uzzzzzzzz
TPP 40-310M2Uzzzzzzzz
TPP 40-321M1Uzzzzzzzz
TPP 40-321M2Uzzzzzzzz
TPP 40-3201Uzzzzzzzz
TPP 40-320M2Uzzzzzzzz
TPP 40-331M3Uzzzzzzzz
TPP 40-3512Uzzzzzzzz
TPP 40-351M2Uzzzzzzzz
TPP 40-210zzzzzzzz
TPP 40-221zzzzzzzz
TPP 40-220zzzzzzzz
TPP 40-231zzzzzzzz
TPP 40-251zzzzzzzz
TPP 40-310M1zzzzzzzz
TPP 40-3102zzzzzzzz
TPP 40-310M2zzzzzzzz
TPP 40-321M1zzzzzzzz
TPP 40-321M2zzzzzzzz
TPP 40-3201zzzzzzzz
TPP 40-320M2zzzzzzzz
TPP 40-331M3zzzzzzzz
TPP 40-3512zzzzzzzz
TPP 40-351M2zzzzzzzz
TPP 40-210Dzzzzzzzz
TPP 40-221Dzzzzzzzz
TPP 40-220Dzzzzzzzz
TPP 40-231Dzzzzzzzz
TPP 40-251Dzzzzzzzz
TPP 40-310M1Dzzzzzzzz
TPP 40-3102Dzzzzzzzz
TPP 40-310M2Dzzzzzzzz
TPP 40-321M1Dzzzzzzzz
TPP 40-321M2Dzzzzzzzz
TPP 40-3201Dzzzzzzzz
TPP 40-320M2Dzzzzzzzz
TPP 40-331M3Dzzzzzzzz
TPP 40-3512Dzzzzzzzz
TPP 40-351M2Dzzzzzzzz

B. Mahrenholz

Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



CERTIFICATE OF COMPLIANCE

Certificate Number E188913
Report Reference E188913-20210203
Issue Date 2022-March-16

TPP 65-210Azzzzzzzz
TPP 65-221Azzzzzzzz
TPP 65-220Azzzzzzzz
TPP 65-231Azzzzzzzz
TPP 65-251Azzzzzzzz
TPP 65-310M1Azzzzzzzz
TPP 65-3102Azzzzzzzz
TPP 65-310M2Azzzzzzzz
TPP 65-321M1Azzzzzzzz
TPP 65-321M2Azzzzzzzz
TPP 65-3201Azzzzzzzz
TPP 65-320M2Azzzzzzzz
TPP 65-331M3Azzzzzzzz
TPP 65-3512Azzzzzzzz
TPP 65-351M2Azzzzzzzz
TPP 65-210Uzzzzzzzz
TPP 65-221Uzzzzzzzz
TPP 65-220Uzzzzzzzz
TPP 65-231Uzzzzzzzz
TPP 65-251Uzzzzzzzz
TPP 65-310M1Uzzzzzzzz
TPP 65-3102Uzzzzzzzz
TPP 65-310M2Uzzzzzzzz
TPP 65-321M1Uzzzzzzzz
TPP 65-321M2Uzzzzzzzz
TPP 65-3201Uzzzzzzzz
TPP 65-320M2Uzzzzzzzz
TPP 65-331M3Uzzzzzzzz
TPP 65-3512Uzzzzzzzz
TPP 65-351M2Uzzzzzzzz
TPP 65-210zzzzzzzz
TPP 65-221zzzzzzzz
TPP 65-220zzzzzzzz
TPP 65-231zzzzzzzz
TPP 65-251zzzzzzzz
TPP 65-310M1zzzzzzzz
TPP 65-3102zzzzzzzz
TPP 65-310M2zzzzzzzz
TPP 65-321M1zzzzzzzz
TPP 65-321M2zzzzzzzz
TPP 65-3201zzzzzzzz
TPP 65-320M2zzzzzzzz
TPP 65-331M3zzzzzzzz
TPP 65-3512zzzzzzzz



Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



CERTIFICATE OF COMPLIANCE

Certificate Number E188913
Report Reference E188913-20210203
Issue Date 2022-March-16

TPP 65-351M2zzzzzzzz
TPP 65-210Dzzzzzzzz
TPP 65-221Dzzzzzzzz
TPP 65-220Dzzzzzzzz
TPP 65-231Dzzzzzzzz
TPP 65-251Dzzzzzzzz
TPP 65-310M1Dzzzzzzzz
TPP 65-3102Dzzzzzzzz
TPP 65-310M2Dzzzzzzzz
TPP 65-321M1Dzzzzzzzz
TPP 65-321M2Dzzzzzzzz
TPP 65-3201Dzzzzzzzz
TPP 65-320M2Dzzzzzzzz
TPP 65-331M3Dzzzzzzzz
TPP 65-3512Dzzzzzzzz
TPP 65-351M2Dzzzzzzzz

Note: "z" may be any alphanumeric character, "-" or blank for market purpose.

TPI 65-105(a)
TPI 65-107(a)
TPI 65-109(a)
TPI 65-112(a)
TPI 65-115(a)
TPI 65-118(a)
TPI 65-124(a)
TPI 65-1L24(a)
TPI 65-128(a)
TPI 65-1L28(a)
TPI 65-136(a)
TPI 65-148(a)
TPI 65-153(a)

Note: (a) - Stands for 6 variables, each variable may be A through Z, 0 through 9, "-", "(", ")", ".", "/" or blank.



Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>

